


XL300 FIRMWARE SERVICE KIT

(For the XL 300, XL 300DD, CX and TX Printers)

Part No. BBF-105967 Rev.A

The firmware service kit contains the controller firmware ROM. The controller firmware consists of a ROM in component location U1. The Controller ROM may be identified by the following label.



The controller firmware ROM is installed on the controller board at the location shown below. Make certain the key pins are oriented as shown below.

